

SMART BUILDINGS GPG BUILDING AND HOME AUTOMATION SOLUTIONS, 2/11/2020

# ABB-Welcome IP

## Release Note Firmware

Product name	IP Touch 10"---HGI17 (View Website)	
Product types	2TMA130051W0004	H8237-8WG
	2TMA130051B0004	H8237-8BG
	2TMA130051W0005	H8237-9WG
	2TMA130051B0005	H8237-9BG
	2TMA130051W0002	H8237-6W
	2TMA130051B0002	H8237-6B
	2TMA130051W0003	H8237-7W
	2TMA130051B0003	H8237-7B
	2TMA130050W0054	H8237-4W
	2TMA130050B0054	H8237-4B
	2TMA130050W0055	H8237-5W
	2TMA130050B0055	H8237-5B
	2TMA130050W0058	H8237-4W-03
	2TMA130050B0058	H8237-4B-03
	2TMA130050W0060	H8237-5W-03
	2TMA130050B0060	H8237-5B-03
Current version	Firmware: 2.10 (Download here <a href="#">[Link]</a> )	

---

ABB releases the firmware 2.10 for ABB-Welcome IP touch 10. Installation is recommended on all Welcome IP systems.

---

## Version 2.10

### New Features

- Added KNXnet/IP Secure feature, which is the secure alternative of KNXnet/IP feature.



Please use for the commissioning password a different one than the tunneling password in the ETS

### Bugfixes

- o Fixes the issue of all linked group addresses send telegrams via KNX bus;
- o Fixes the issue of Fan controlling (under certain conditions, no telegram send out when turn off Fan)
- o Fixes the issue of WW/CW controlling;
- o Fixes the issue of some German translation were not accurate.

- o Fixes the issue of free@home, If a user who has no installation rights connecting to IP touch panel, an endless connecting are visible and connection not possible.

#### FIRMWARE HISTORY

Product Type	Version	Since	Updates and Release Notes
IP Touch 10"	2.10	12/2020	Update

## Installation Instructions

- Please refer to system manual ([link](#))